






Assembly Instructions


QI003456




NO.	QTY.	L INEDRAWING	DESCRIPTION
A	10		
B	2		
C	42		
D	16		
E	4	 3.5*35	
F	4	 6*60	
G	4		
H	2		
I	4		
J	2		
K	6		




1


 $A*2+B*2$


2


 $A*4$

3



 $A*4$

4



 $C*6+K*6$

5



J





6



7



8



9

