











Assembly Instructions

QI003458




NO.	QTY.	LINEDRAWING
A	28	
B	3	
C	5	<p>3.5*30</p> 
D	23	<p>3.5*14</p> 
E	5	
F	28	
G	3	
H	1	




NO.	QTY.	L I N E D R A W I N G
1	1	
2	1	
3	1	
4	1	
5	1	
6	1	

1




$A*12+F*12$

2




$A*16+F*16$

3




$C*5+E*5$

4




$B*3+D*23+H*1$

5



6



G*3